



## TOP VIEW DIRECTOR 4 6 REFLECTOR

## \*The reflector must be on the side of the box

## **SIDE VIEW**





## www.proskypper.com Assembly parts manual

- 1 4 way cross connector for fiberglass rods.
- 2 Aluminium mast pole.
- 3 Aluminium dipole box, with PL connector for  $50\Omega$  coaxial cable.
- 4 Fiberglass rods.
- **5** Dipole wire.
- 6 Director and reflector wire. The red wire is the director side.
- Tie rod between director and reflector





